


FIG. 1






FIG. 3




FIG. 4




FIG. 5A




FIG. 5B







FIG. 6

	THROTTLE IS POSITIONED IN ENGINE COMPARTMENT				THROTTLE IS POSITIONED IN VICINITY OF EVAPORATOR			
EVAPORATOR CONDITION	BLOWER INLET TEMPERATURE: 35.1°C EVAPORATOR PRESSURE: 4.7MPa				BLOWER INLET TEMPERATURE: 29.2°C EVAPORATOR PRESSURE: 4.8MPa			
BLOWN AIR TEMPERATURE	PASSENGER'S SEAT SIDE	PASSENGER'S SEAT CENTER	DRIVER'S SEAT CENTER	DRIVER'S SEAT SIDE	PASSENGER'S SEAT SIDE	PASSENGER'S SEAT CENTER	DRIVER'S SEAT CENTER	DRIVER'S SEAT SIDE
	<u>21.1°C</u>	19.2°C	<u>17.7°C</u>	17.9°C	15.2°C	14.6°C	<u>14.0°C</u>	<u>15.5°C</u>
POST-EVAPORATOR AIR TEMPERATURE								



**FIG. 8**

